## **CONTRACT CHANGE ORDER MEMORANDUM**

TO: Pete Sieger	nthaler, F	rin TE /			FILE:	E.A.	04 - 0120F4			
						re-PM	SF-80-13.2/13.9			
FROM: Gary Pursell, Sup. TE					FEI	D. NO.				
CCO#: <b>48</b>	SUPPL	EMENT#: 0	Category	Code: CHSA	CONTIN	CONTINGENCY BALANCE (incl. this change) \$48,100,323.40				
COST: \$531,137.00 INCREASE ☑ DECREASE □					HEADQU	HEADQUARTERS APPROVAL REQUIRED?			S NO	
SUPPLEMENTAL FUNDS PROVIDED: \$0.00					The second of the second of	IS THIS REQUEST IN ACCORDANCE WITH    ✓ YES    NO ENVIRONMENTAL DOCUMENTS?				
CCO DESCRIPTION:						PROJECT DESCRIPTION:				
Tower Strut Façade						CONSTRUCT SELF-ANCHORED SUSPENSION BRIDGE				
Original Contract Time:		Time Adj. This Change: Previously Approved Co		d CCO		tage Time Adjusted: ng this change)		econciled Deferred Time uding this change)		
2490	Day(s)	0	Day(s)	227	Day(s)		9 %		6	

DATE: 12/1/2009

Page 1 of 2

## THIS CHANGE ORDER PROVIDES FOR:

Providing polytetrafluoro-ethylene (PTFE) film at the interface between the seal angles and the top and bottom Tower façade plates. Installing bolts at the PTFE connections that are snug-tight.

In Special Provisions Section 10-1.59 "STEEL STRUCTURES," subsection "FABRICATION," subsection "Bolted Connections," add bullet "Q" as follows:

"Q. At the option of the Contractor, Extra Thick style washers may be used in lieu of standard thickness Circular style washers. Extra Thick style washers shall conform to all the requirements of ASTM F 436M, except the thickness shall be accordance with ASTM F 436."

The Designer's original intent was to have PTFE at the Tower façade plates, but it was not reflected in the Contract documents. Since the F436M specifications do not provide a metric dimension for "double thick" washers, Special Provisions is revised to address this issue.

This change order resolves the costs associated with Contractor Request For Information (RFI) numbers 761, 935R0, 935R1, 935R2, 935R3, 935R4, 1186, 1614, and 2169 with respect to changes listed above.

The total cost of this change order is \$531,137.00, which can be financed from the contingency fund. A detailed cost analysis is on file.

No time adjustment is warranted as this change order does not affect the controlling operation.

This change order has concurrence from Gary Pursell (Resident Engineer), Rick Morrow (Supervising Bridge Engineer), Peter siegenthaler (Principal TE), Ken Terpstra (Project Manager), Wenyi Long (Design Oversight), Bill Zanetich (Structure Maintenance) and Rich Foley (HQ Oversight).

EA: 0120F4 CCO: 48 - 0

DATE: 12/1/2009

Page 2 of 2

CONCURRED BY:			ESTIMATE OF COST					
Construction Engineer:	Res. Eng., Gary Pursell, Sup. TE	Date	8/17/07		THIS REQUEST	TOTAL TO DATE		
Bridge Engineer:	Struct Rep, Rick Morrow, Sup TE	Date	8/16/07	ITEMS	\$0.00	\$0.00		
Project Engineer:	CT Oversight, Wenyi Long, P.E.	Date	8/24/07	FORCE ACCOUNT AGREED PRICE	\$0.00	\$0.00		
Project Manager:	Proj Manager, Ken Terpstra	Date	8/25/07	ADJUSTMENT	\$0.00 \$531,137.00	\$0.00 \$531,137.00		
FHWA Rep.:	HQ, Rich Foley	Date	8/10/10	TOTAL	\$531,137.00	\$531,137.00		
Environmental:		Date			FEDERAL PARTICIPATION	N .		
Other (specify):	PCE, Pete Siegenthaler, Prin TE	Date	8/20/07	PARTICIPATING	PARTICIPATING IN			
Other (specify):	(specify): Struct Maint, Bill Zanetich, P.E.		8/29/07	NON-PARTICIPATING (MAINTENANCE) NON-PARTICIPATING  FEDERAL SEGREGATION (if more than one Funding Source or P.I.P. type)				
District Prior Approval By:				CCO FUNDED PER		CO FUNDED AS FOLLOWS		
HQ (Issue Approve) By:		Date		FEDERAL FUNDING	SOURCE	PERCENT		
Resident Engineer's Signature:		Date						
136	ST REFIL	8/1	0/10	-				